Current Opportunities at MMS

CNC Electrician – Must have a proven history of trouble shooting, making repairs and adjustments to CNC machine tool controls, drives and related devices.

CNC Machine Repair – Must have 5+ year's experience trouble shooting and repairing CNC machine tool mechanical components. Must have experience replacing way bearings, ballscrews, adjusting machine geometry and repairing hydraulic components. Experience in scraping is a plus.